Message Text

UNCLASSIFIED

PAGE 01 QUITO 05796 181711Z ACTION ARA-14

INFO OCT-01 ISO-00 SOE-02 AID-05 CEA-01 CIAE-00 COME-00 DODE-00 EB-08 DOE-15 H-02 INR-10 INT-05 L-03 NSAE-00 NSC-05 OMB-01 PM-05 ICA-20 OES-09 SP-02 SS-15 STR-07 TRSE-00 ACDA-12 PA-02 /144 W -------035377 191803Z /42

R 181625Z AUG 78 FM AMEMBASSY QUITO TO SECSTATE WASHDC 9156 INFO AMCONSUL GUAYAQUIL

UNCLAS QUITO 5796

E.O. 11652: N/A TAGS: ENRG. EC

SUBJECT: BREAK IN TRANS-ANDEAN PIPELINE

- 1. A RUPTURE IN THE TRANS-ANDEAN PIPELINE ON AUGUST 14 AT ABOUT 5:30 A.M. HAS CAUSED THE FLOW OF CRUDE PETROLEUM FROM THE TEXACO/CEPE (STATE PETROLEUM CORPORATION) FIELDS IN THE ORIENTE TO FALL FROM 217,000 BPD TO A LEVEL NEAR 30,000 BPD (THE REMAINING PRODUCTION COMES FROM FIELDS DOWN THE LINE).
- 2. THE BREAK OCCURRED WHERE THE PIPELINE CROSSES THE BOTTOM OF THE AGUARICO RIVER. HEAVY RAINFALL ON AUGUST 14 CAUSED THE RIVER TO RISE TO A LEVEL OF 20 FEET, SOME 15 FEET ABOVE NORMAL, THUS DELAYING REPAIRS. TEXACO NOW EXPECTS TO HAVE THE LINE BACK IN FULL OPERATION BY ABOUT NOON ON AUGUST 19, FOR A TOTAL DOWN-TIME OF 5.25 DAYS. WITH THE DAILY OUTPUT LOSS OF 187,000 HPD, THE TOTAL PRODUCTION LOSS SHOULD APPROXIMATE 980,000 BARRELS, MEANING A DECLINE OF 31,000 BPD FOR THE AUGUST DAILY PRODUCTION FIGURE.
- 3. TEXACO PLANS TO BUILD A STAND-BY PARALLEL LINE UNDER THE RIVER AS A PRECAUTION AGAINST FURTHER PROBLEMS IN THE SAME SPOT. UNCLASSIFIED

UNCLASSIFIED

PAGE 02 QUITO 05796 181711Z

4. THIS LATEST BREAK, FOLLOWING A FEW MINOR ONES EARLIER THIS YEAR, UNDERSCORES THE VULNERABILITY OF ECUADOR'S ECONOMY SHOULD THE LINE BE SHUT DOWN FOR AN EVEN LONGER PERIOD OF TIME.

GONZALEZ

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X Capture Date: 01 jan 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: PETROLEUM PIPELINES, OIL SPILLS

Control Number: n/a
Copy: SINGLE
Draft Date: 18 aug 1978
Decaption Date: 01 jan 1960
Decaption Note: Disposition Action: n/a

Disposition Approved on Date: Disposition Case Number: n/a Disposition Comment: Disposition Date: 01 jan 1960 Disposition Event: Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978QUITO05796
Document Source: CORE

Document Unique ID: 00 Drafter: n/a

Enclosure: n/a Executive Order: N/A Errors: N/A

Expiration: Film Number: D780340-0415 Format: TEL

From: QUITO

Handling Restrictions: n/a

Image Path: ISecure: 1

Legacy Key: link1978/newtext/t19780848/aaaabobc.tel

Line Count: 61 Litigation Code IDs: Litigation Codes:

Litigation History: Locator: TEXT ON-LINE, ON MICROFILM Message ID: 9e5de360-c288-dd11-92da-001cc4696bcc

Office: ACTION ARA

Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a

Page Count: 2
Previous Channel Indicators: n/a Previous Classification: n/a
Previous Handling Restrictions: n/a

Reference: n/a Retention: 0

Review Action: RELEASED, APPROVED Review Content Flags:

Review Date: 29 mar 2005 **Review Event:** Review Exemptions: n/a **Review Media Identifier:** Review Release Date: N/A

Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

SAS ID: 1694117 Secure: OPEN Status: NATIVE

Subject: BREAK IN TRANS-ANDEAN PIPELINE

TAGS: ENRG, EC To: STATE Type: TE

vdkvgwkey: odbc://SAS/SAS.dbo.SAS_Docs/9e5de360-c288-dd11-92da-001cc4696bcc

Review Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014

Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014